

➤ **Vendor: Cisco**

➤ **Exam Code: 300-615**

➤ **Exam Name: Troubleshooting Cisco Data Center Infrastructure (DCIT)**

➤ **New Updated Questions from [Braindump2go](https://www.braindump2go.com)**

➤ **(Updated in [December/2021](#))**

Visit Braindump2go and Download Full Version 300-615 Exam Dumps

QUESTION 123

Refer to the exhibit. A customer network uses OSPFv2 and MP-BGP protocols. A network administrator installs a new Cisco Nexus Switch in the data center but experiences a BGP RIB failure. Which action solves the issue?

```
DC-1#show ip bgp | include r>
BGP table version is 5232, local router ID is 10.9.7.13
Status codes: s suppressed, d damped, h history, * valid, > best, i - internal,
               r - RIB-failure, S Stale, m multipath, b backup-path, f RT-Filter,
               x - best-external, a additional-path, c RIB-compressed,
Origin codes: i - IGP, e - EGP, ? - incomplete
RPKI validation codes: V valid, I invalid, N Not found

   Network          Next Hop           Metric LocPrf Weight Path
r>i 209.165.200.226/27    10.8.5.7              0    100      0 i
r>  209.165.201.30/27    10.2.7.9              0          0 65001 i
DC-1#

DC-1#show ip route 209.165.200.226
Routing entry for 209.165.200.226/27
  Known via "ospf 1", distance 110, metric 20, type intra area
  Last update from 10.0.5.5 on FastEthernet0/0, 01:13:27 ago
  Routing Descriptor Blocks:
    * 10.0.5.5, from 209.165.200.226, 01:13:27 ago, via Ethrenet0/5
      Route metric is 20, traffic share count is 1
DC-1#
```

- A. Change the administrative distance of OSPF to 220
- B. Configure the route as a BGP backdoor
- C. Use a filter list for OSPF to filter both routes
- D. Implement next-hop-self

Answer: D

QUESTION 124

An engineer is implementing a new BGP peering in their new data center. The engineer set up the BGP session that peers with the remote end. As soon as the BGP peers attempt to exchange routing prefixes, one of the BGP peers drops the connection. After reviewing the configuration, the engineer reviews the logging messages. The engineer discovers that the router is missing keepalives from the remote end and terminates the session. Which action resolves the issue?

- A. Set the **bgp transport path-mtu-discovery** attribute on both peers
- B. Set the higher values for the BGP keepalive and hold-down timers on both peers

[300-615 Exam Dumps](#) [300-615 Exam Questions](#) [300-615 PDF Dumps](#) [300-615 VCE Dumps](#)

<https://www.braindump2go.com/300-615.html>

- C. Configure the matching BGP AS numbers between the peers
- D. Configure the matching BGP passwords between the peers

Answer: B

QUESTION 125

Refer to the exhibit. The vPC neighborship between two switches is in suspended state. Which configuration change resolves the issue and brings up the vPC neighborship?

```
switch1# show vpc consistency-parameters global
```

Legend:
Type 1 : vPC will be suspended in case of mismatch

Name	Type	Local Value	Peer Value
Qos	1	([], [3], [], [], [], [])	([], [3], [], [], [], [])
Network QoS (MTU)	1	(9216, 2240, 0, 0, 0, 0)	(9116, 2240, 0, 0, 0, 0)
Network QoS (Pause)	1	(F, T, F, F, F, F)	(F, T, F, F, F, F)
Input Queuing (Bandwidth)	1	(50, 50, 0, 0, 0, 0)	(50, 50, 0, 0, 0, 0)
Input Queuing (Absolute Priority)	1	(F, F, F, F, F, F)	(F, F, F, F, F, F)
Output Queuing (Bandwidth)	1	(50, 50, 0, 0, 0, 0)	(50, 50, 0, 0, 0, 0)
Output Queuing (Absolute Priority)	1	(F, F, F, F, F, F)	(F, F, F, F, F, F)
STP Mode	1	Rapid-PVST	Rapid-PVST
STP Disabled	1	None	None
STP MST Region Name	1	""	""
STP MST Region Revision	1	0	0
STP MST Region Instance to VLAN Mapping			
STP Loopguard	1	Disabled	Disabled
STP Bridge Assurance	1	Enabled	Enabled
STP Port Type, Edge	1	Normal, Disabled	Normal, Disabled
BPDUFILTER, Edge BPDUGuard		Disabled	Disabled
STP MST Simulate PVST	1	Enabled	Enabled
Allowed VLANs		1,19,91,99,120,757-446 451-486,499,757,797	1,10,19-20,91,99,400-401 403,420,440,442,444
Local suspended VLANs		120	

- A. Change STP Port Type to Network on the peer switch
- B. Enable Bridge Assurance on the local switches
- C. Configure QoS MTU value of 9216 on the peer switch
- D. Add VLAN 400-401 to the configuration on the local switch

Answer: C

QUESTION 126

Refer to the exhibit. The integration between Cisco UCS Manager and Cisco UCS Central failed. Which action resolves the issue?

UCS Central Registration

Policy Resolution Control

FSM Status

: In Progress

Description

:

Current FSM Name

: Repair Cert

Completed at

:

Progress Status

:

0%

Remote Invocation Result

: Resource Unavailable

Remote Invocation Error Code

: 5

Remote Invocation Description

: UCSM and UCS Central time is not synchronized. Retrying...

Step Sequence


Order	Name	Description	Status	Timestamp	Retried
1	Repair Cert Verify Guid	verifying GUID of UCS Ce...	In Progress		1
2	Repair Cert Unregister		Pending		0
3	Repair Cert Clean Old Data		Pending		0
4	Repair Cert Request		Pending		0
5	Repair Cert Verify		Pending		0

- A. Implement the consistent NTP source between the appliances
- B. Implement the connectivity between the appliances through a firewall
- C. Configure the certificate between the appliances
- D. Configure the shared secret key between the appliances

Answer: A

QUESTION 127

Refer to the exhibit. An engineer fails to implement a Cisco UCS Manager integration manager. The credentials and IP connectivity between Cisco APIC and UCS Manager are configured as expected. Which action resolves the issue?



Fault Properties

General Troubleshooting History

Fault Code: F3208

Severity: major

Last Transition: 2020-07-07T14:42:49.161+03:00

Lifecycle: Soaking

Affected Object: edm/Mgr-[UCS_C1]-UCS_C1

Description: Fault delegate: Connection to External Device: 172.16.105.50 with name UCS_C1 is failing to connect with the error: [Failed to connect with Integration Manager]. Please verify network connectivity of External Device and that user credentials are valid.

Type: Communications

Cause: connect-failed

Change Set: issues (Old: , New: connection-fault)

Created: 2020-07-07T14:42:49.161+03:00

Code: F3208

Number of Occurrences: 1

Original Severity: major

Previous Severity: major

Highest Severity: major

- A. Disable HTTP to HTTPS redirection in Cisco UCS Manager
- B. Enable JSON API on the Cisco UCS Manager
- C. Change the Integration Manager name to FQDN of the Cisco UCS Manager
- D. Install ExternalSwitch app in the APIC controller

Answer: D

QUESTION 128

A network engineer experiences the error "DDR3_P1_B1_ECC" when upgrading Cisco UCS firmware. Which action resolves the issue?

- A. Reset the DIMM
- B. Reset the BMC firmware
- C. Reflash the controller firmware
- D. Reflash the DIMM

Answer: A

QUESTION 129

Refer to the exhibit. A Cisco UCS Fabric Interconnect fails during the upgrade process. The working images of the fabric interconnect are stored on the bootflash. Which set of commands recovers the fabric interconnect?

```
Booting kickstart image: bootflash:/installables/switch/ucs-6100-k9-kickstart.4
.1.2.N2.1.11.bin....Loader Version pr-1.3

loader> dir
bootflash:
  lost+found
  ucs-6100-k9-kickstart.4.1.3.N2.1.11.bin
  ucs-6100-k9-system. 4.1.3.N2.1.11.bin
  sysdebug
  chassis.img
  nuova-sim-mgmt-nsg.0.1.0.001.bin
  pnuos
  installabels
  mts.log
  vdc_2
  vdc_3
  vdc_4
  distributables
  initial_setup.log
  tmp
  .tmp-kickstart
  .tmp-system

loader>
```

- A. loader> **dir**
loader> **boot ucs-6300-k9-kickstart.5.0.2.N1.3.02d56.bin**
switch(boot)# **init system**
switch(boot)# **reload**
switch(boot)# **load ucs-6300-k9-system.5.0.2.N1.3.02d56.bin**
- B. loader> **dir**
loader> **boot ucs-6300-k9-kickstart.5.0.2.N1.3.02d56.bin**
switch(boot)# **copy ics-manager-k9.1.4.1k.bin nuova-sim-mgmt-nsg.0.1.001.bin**
switch(boot)# **boot ucs-6300-k9-system.5.0.2.N1.3.02d56.bin**
- C. loader> **dir**
loader> **boot ucs-6300-k9-kickstart.5.0.2.N1.3.02d56.bin**
switch(boot)# **init system**
switch(boot)# **reload**
switch(boot)# **boot ucs-6300-k9-system.5.0.2.N1.3.02d56.bin**
- D. loader> **dir**
loader> **boot ucs-6300-k9-kickstart.5.0.2.N1.3.02d56.bin**
switch(boot)# **copy ics-manager-k9.1.4.1k.bin nuova-sim-mgmt-nsg.0.1.001.bin**
switch(boot)# **load ucs-6300-k9-system.5.0.2.N1.3.02d56.bin**

Answer: D

QUESTION 130

Refer to the exhibit. An engineer monitors a Cisco UCS server logs and discovers a blade discovery issue. Which procedure resolves the issue?

```
Unable to change server power state-MC
Error(-20): Management controller cannot or
failed in processing
request(sam:dme:ComputePhysicalTurnup:Execute
)
```


```
[ help ]# power
OP:[ status ]
Power-State:          [ on ]
VDD-Power-Good:       [ active ]
Power-On-Fail:        [ inactive ]
Power-Ctrl-Lock:      [ unlocked ]
Power-System-Status:  [ Good ]
Front-Panel Power Button: [ Enabled ]
Front-Panel Reset Button: [ Enabled ]
OP-CCODE: [ Success ]
[ power ]#
```

- A.
 - 1. Verify the server power module.
 - 2. Decommission the faulty module.
 - 3. Insert a new power module.
 - 4. Recommission the new module.
- B.
 - 1. Verify that server platform power is failed
 - 2. Resolve the platform power issue.
 - 3. Reboot the server.
 - 4. Recommission the server.
- C.
 - 1. Verify the FSM status on the server.
 - 2. Decommission the impacted server.
 - 3. Reset the slot where the server is located.
 - 4. Recommission the server.
- D.
 - 1. Verify that the power on self-test operation is failed.
 - 2. Verify that the server firmware is corrupted.
 - 3. Decommission the server firmware
 - 4. Recommission the server with new firmware.

Answer: C

QUESTION 131

Refer to the exhibit. A network engineer finds one of the fabric interconnects offline when connecting L1 and L2 ports on both fabric interconnects. Which action resolves the issue?



- A. 1. Connect to Fabric Interconnect B.
2. Verify the cluster status and HA election.
3. Validate Fabric Interconnect B hardware issues.
- B. 1. Connect to Fabric Interconnect A.
2. Verify the cluster status and HA election.
3. Validate Fabric Interconnect A hardware issues.
- C. 1. Connect Fabric Interconnect B and change the role to primary.
2. Reboot Fabric Interconnect B.
3. Add the Fabric Interconnect A as subordinate fabric to the cluster.
- D. 1. Connect Fabric Interconnect B and execute "Erase configuration"
2. Reboot Fabric Interconnect B.
3. Add the subordinate Fabric Interconnect to the cluster.

Answer: D

QUESTION 132

Refer to the exhibit. A network engineer upgrades the firmware of a Cisco Fabric Interconnect from boot flash. During the process, the fabric interconnect reboots and displays the message shown in the exhibit. Which action resolves the issue?

```
Booting kickstart image: bootflash:/nxos.7.0.3.I7.4.bin
CardIndex = 11056

Couldn't read file. Expected 392e9000 Got ffffffff
File does not exist, boot failed.

error: Vendor info. Expected 1024 Read-1

loader>
```

- A. Remove the service pack and upgrade through the auto-install procedure

[300-615 Exam Dumps](#) [300-615 Exam Questions](#) [300-615 PDF Dumps](#) [300-615 VCE Dumps](#)

<https://www.braindump2go.com/300-615.html>

- B. Reset the I/O module and install the firmware image from the boot flash
- C. Boot the kickstart image from boot flash and load the system image
- D. Reload the switch and boot the kickstart image from the TFTP server

Answer: D

QUESTION 133

Refer to the exhibit. A Cisco UCS B-Series Blade Server is configured to boot from a shared storage via an iSCSI network. When a service profile is associated with the blade, the blade fails to attach the LUN. Which action resolves the issue?

```
UCS-LAB-IC-1-A# connect adapter 1/1/1
adapter 1/1/1 # connect
No entry for terminal type "vt220";
using dumb terminal settings.

adapter 1/1/1 (top):1# attach-mcp
No entry for terminal type "vt220";
using dumb terminal settings.

vnic iSCSI Configuration:
-----

vnic_id: 5
      link_state: Up

      Initiator Cfg:
        initiator_state: ISCSI_INITIATOR_READY
        initiator_error_code: ISCSI_BOOT_NIC_NO_ERROR
          vlan: 0
        dhcp status: false
          IQN: iqn.2013-01.com.myserver124
          IP Addr: 10.68.68.2
          Subnet Mask: 255.255.255.0
          Gateway: 10.68.68.254

Target Cfg:
  Target Idx: 0
    State: INVALID
    Prev State: ISCSI_TARGET_GET_LUN_INFO
  Target Error: ISCSI_TARGET_GET_HBT_ERROR
    IQN: iqn.1992-08.com.netapp:sn.1111111
    IP Addr: 10.78.78.20
    Port: 3260
    Boot Lun: 0
    Ping Stats: Success (8.112ms)
```

- A. Place VLAN 0 on the interface that connects to the storage

[300-615 Exam Dumps](#) [300-615 Exam Questions](#) [300-615 PDF Dumps](#) [300-615 VCE Dumps](#)

<https://www.braindump2go.com/300-615.html>

- B. Register the blade as an initiator on the storage array
- C. Implement a Layer 3 connection between the blade and the storage
- D. Establish a Layer 2 connection between the blade and the storage

Answer: D

QUESTION 134

Refer to the exhibit. A network engineer is implementing a Cisco UCS environment. The environment consists of eight servers configured with the same service profile template and Windows 2012 installed. The VFC interfaces of five of these servers are showing the error shown in the exhibit. Which action resolves the issue?

```
FI-A(nxos)# show int vfc 952
vfc952 is down (Error Disabled - VLAN L2 down on Eth interface)
Bound interface is Vethernet9155
Port description is server 1/5, VHBA fc0
Hardware is Ethernet
Port WWN is 23:c2:00:de:fb:2b:e6:ff
Admin port mode is F, trunk mode is on
snmp link state traps are enabled
Port vsan is 100
1 minute input rate 0 bits/sec, 0 bytes/sec, 0 frames/sec
1 minute output rate 0 bits/sec, 0 bytes/sec, 0 frames/sec
0 frames input, 0 bytes
0 discards, 0 errors
0 frames output, 0 bytes
0 discards, 0 errors
```

- A. Modify the vHBAs name in the storage connectivity policy
- B. Configure upstream zoning
- C. Decommission and recommission the servers
- D. Modify the boot order in the boot policy

Answer: A

QUESTION 135

Refer to the exhibit. A client configures an upgrade of its Cisco Nexus switches that are connected to the Cisco ACI controller, such that the switches are upgraded one at a time. After the upgrade is run, it is discovered that both Cisco Nexus switches were upgraded simultaneously. Which two actions ensure that the switches upgrade one at a time? (Choose two.)

Schedule Node Upgrade

Group Type: Switch vPod

Upgrade Group Name: DC_Lab

Target Firmware Version: aci-n900-dk9.14.2.2a.b


Ignore Compatibility Check: ☐

Graceful Maintenance: ☐

Run Mode: Do not pause on failure and do not wait on cluster health Pause upon upgrade failure

Upgrade Start Time: Now Schedule For Later

Node Selection: Range Manual



```

graph TD
    spine-1 --- leaf-1
    spine-1 --- leaf-2
    leaf-1 --- APIC-1
    leaf-2 --- APIC-1
    
```

All Nodes

Selected	ID	Name	Role	Model	Current Firmware	Target Firmware	Status
<input checked="" type="checkbox"/>	Pod1/101	leaf-1	leaf	N9K-C9396PX	4.1(1k)		Not Scheduled
<input checked="" type="checkbox"/>	Pod1/101	leaf-2	leaf	N9K-C9396PX	4.1(1k)		Not Scheduled
<input checked="" type="checkbox"/>	Pod1/201	spine-1	spine	N9K-C9508	4.1(1k)		Not Scheduled

- A. Configure the "Do not pause on failure and do not wait on cluster health" Run Mode
- B. Choose the "Pause upon upgrade failure" Run Mode
- C. Select the "Graceful Maintenance" checkbox
- D. Place each leaf switch in a different upgrade group
- E. Check the "Ignore Compatibility" checkbox

Answer: BD

QUESTION 136

Refer to the exhibit. An engineer configures the server port on a Cisco Nexus 5000 Series Switch. The switch connects to an NPV edge switch port. The server fails to send the FC traffic to the fabric. Which action resolves the issue?

```

Test-5548-A# sh int fc2/12
sh int fc2/12 is down (NPV upstream port not available)
Hardware is Fibre Channel, SFP is short wave laser w/o OFC (SN)
Port WWN is 20:47:00:0d:ec:a4:3b:80
Admin port mode is F, trunk mode is off
snmp link state traps are enabled
Port vsan is 99
Receive data field Size is 2112

```

- A. Enable the NPIV mode on the Cisco Nexus 5000 switch.
- B. Match the VSAN membership on both ends of the connection.
- C. Configure the BB_credit buffer on the uplink port.
- D. Replace the SFP in slot fc2/12.

Answer: B